Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	4	"5887851"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 11:26
L2	6	("5226221" "5331730" "5423117" "5533249").PN. OR ("5887851").URPN.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:26
L3	1455	251/129.15.ccls.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:27
L4	167	3 and (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 cell gage gauge)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:45
L5	.44	4 and (hydraulic)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:44
L6	33	5 and (housing casing frame)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:28
L7 .	1	1 and (sens\$4 detect\$4 transducer measur\$4 cell gage gauge)	US-PGPUB; USPAT; USOCR	OR .	ON	2006/12/04 11:32
L8 .	28	3 and (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 cell gage gauge).clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:34
L9	3	8 and (hydraulic).clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:38
L10	5841	(hydraulic) near3 (housing casing frame).clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:48
L11	331	10 and (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 cell gage gauge).clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:48
L12	107	11 and (duct port hole orifice). clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:49
L13 ·	. 13	12 and (nut bolt screw fasten\$4). clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:49

L14	25587	(hydraulic) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:48
L15	3753	14 and (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 cell gage gauge)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:48
L16	1124	15 and (pressure) near3 (duct port hole orifice)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:49
L17	749	16 and (nut bolt screw fasten\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:50
L18	221	17 and (brak\$4)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:55
L19	158	18 and (flange edge)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:50
L20	152	19 and (recess\$4 hole aperture opening)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:51
L21	87	20 and (metal\$4 steel brass)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:51
L22	46	21 and (pipe)	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:51
L23	10	12 and (brak\$4).clm.	US-PGPUB; USPAT; USOCR	OR	ON	2006/12/04 11:55

12/4/06 11:56:41 AM Page 2

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2934	251/129.15.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 11:57
L2	22	1 and (plural\$4 array couple multiple several second two) near3 (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:04
L3	7	2 and (hydraulic)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON ·	2006/12/04 12:09
L4	361	73/121.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:01
L5	34	4 and (plural\$4 array couple multiple several second two) near3 (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:01
L6	16	5 and (hydraulic)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:05
L7	3	4 and (hydraulic) near3 (housing casing frame)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:04
L8	174	4 and (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR .	ON	2006/12/04 12:08
L9	60	8 and (hydraulic)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:05

L10	203	1 and (pressure load force strain stress) near3 (sens\$4 detect\$4 transducer measur\$4 gage gauge cell)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:09
L11	48	10 and (hydraulic)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2006/12/04 12:09

Page 2